

January 7, 2010

Duane Allen, Director of Public Works City of Eureka Springs 3174 E. Van Buren Eureka Springs, AR 72632

RE: AFIN: 08-00036 NPDES Permit No.: AR0021865

Dear Mr. Allen:

On December 31, 2009, I performed a reconnaissance inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection revealed the following violations:

- 1. The plant was violating Part 1 Section A of the facility Permit. The effluent limitations and monitoring requirements of the permit were being violated by discharging effluent to Leatherwood Creek with distinctly visible solids, floating grease and sludge banks.
- 2. Part II Section C.6 requires the permittee to report any noncompliance which may endanger health or the environment. An oral report to the Director is required within 24 hours and a written report is required within 5 days of the time the permittee becomes aware of the circumstances. No report of noncompliance was received by the Department.

The above items require your immediate attention. You must submit a written response to the findings to the Attention of Cindy Garner, Water Division Enforcement Branch Manager of ADEQ.

This response must contain detailed documentation describing the course of action taken to correct the violations noted. This corrective action should be completed as soon as possible, and the written response is due by January 18, 2010. For additional information you may contact the enforcement section by telephone at 501-682-0639 or by fax at 501-682-0910.

If you have any questions concerning this correspondence you may contact me at 870-446-2770 or by e-mail at morris@adeq.state.ar.us.

Sincerely,

Tony L. Morris

District 2 Field Inspector

morn L morns

ADEQ Water Division

cc: Water Division Permits Branch

Water Division Enforcement Branch

3	<b>⊕</b> EPA															proved 040-000	)3		
		UNIT	ED STATE	ES ENVIRONN	MENTAL	PROTEC	CTION A	GENCY											
	NDDE	c (	Y	Washingto	,		00 <b>4</b> :	<b></b>	Danar	.4									
	NPDE	<u> </u>	\OIII]	pnanc	e II	usp	ecu	OII	Kepor	ι									
					Section	A: Na	ational	Data S	ystem Codi										
1	Transaction Code  N 2 5 3 A R	0	0 2	NPDES 1 8	6	5	11 1	2 0	9 1	/Mo/Da	у 3	1	17	Insp 18	R R	19	nspect	or I 20	ac. Type
	0 8 - 0 0 0	3	6				Ren	narks											
Inspection Work Days Facility Evaluation Rating BI QA											I	Reserved							
	67 69		70	2			71 <b>I</b>	72	<b>N</b> 73	Ш		74	75		80				
	Section B: Facility Data																		
incl	ne and Location of Facility Inspected ude POTW name and NPDES permit City of Eureka Springs POTW is	numi	ber)						Entry Tin 11:20 De		31, 2	2009				Permit Effective Date December 1, 2007			
Cou	nty.								Exit Time 12:15 De		31, 2	2009			Permit Expiration Date November 30, 2012				
	ne(s) of On-Site Representative(s)/Tite Wegrzyn, Plant Operator 479-2			nd Fax Nur	mber(s)									N 3	her Facility Data 36.4196 93.7346				
	ne, Address of Responsible Official/		Phone an	d Fax Num	ber									",					
	ne Allen, Director of Public Work of Eureka Springs	S								Contac	eted								
	4 E. Van Buren eka Springs, AR 72632 Phone:	479-2	253-9600	)					Yes No No										
	<u> </u>								<u> </u>										
			(S =						<b>uring Inspe</b> isfactory, N		Evalu	ated)							
S	Permit	U	Flow N	Measureme	ent		τ	J OF	erations &	Mainte	nanc	e		N	N Sampling				
N	Records/Reports	U	Self-M	Ionitoring	Progra	m	τ	J Sh	udge Handling/Disposal N				Pollution Prevention						
U	Facility Site Review	N	Comp	liance Scho	edules		ľ	N Pr	Pretreatment				N	Multimedia					
U	Effluent/Receiving Waters	N	Labor				ľ	Di	Storm Water N					Other: Discharge Limits					
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)																			
<ul> <li>Leatherwood Creek was visited due to citizen complaints concerning discolored and foamy water. The complaint was found to be valid. Conspicuous banks, of distinctly gray colored activated sludge was observed in eddies within the creek down stream of the POTW.</li> <li>Upon entering the treatment plant site, a large volume of spilled sludge was observed flowing to the creek. The discharge of sludge has been occurring for some time and the noncompliance has not been reported or addressed.</li> </ul>																			
- The flow totalizer was found to be turned off. Plant discharges were not being recorded.																			
	<ul> <li>One bank of UV Sterilizer lights were noted to be turned off.</li> <li>A large volume of dewatered sludge was observed to be stored in the filter press building. The material had been stored long enough for seeds within</li> </ul>												ithin						
	the sludge to sprout.																		
Naı	me(s) and Signature(s) of Inspector(s	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality- Jasper Field Office							Date January 4, 2010										
Ton	y L. Morris Vong L Mon	b				•			0-446-2181	-	1.10	u Ol			Janual	, 7, 20	,10		
Sig	nature of Reviewer	Agency/Office/Phone and Fax Numbers							Date										

Water Division NPDES Photographic Evidence Sheet											
Location: Eureka Springs POTW, Carroll County											
Photographer:		Tony N	<i>I</i> orris		Witness:	None					
<b>Photo</b> # 1		Of	8		Date:	12/31/09	11:42				
<b>Description:</b>		The pla	ant headw	vorks filled with grit and r	on function	ing at the time	of the inspe	ction.			



 Photographer:
 Tony Morris
 Witness:
 None

 Photo #
 2
 Of
 8
 Date:
 12/31/09
 Time:
 11:30

**Description:** The effluent flow totalizer turned off.



<b>Location:</b>	Eu	ureka Springs POTW, Carroll County									
Photograph	er:	Tony N	Morris		Witness:	None					
Photo #	3	Of	8		Date:	12/31/09	Time:	11:50			
<b>Description:</b> Spilled sludge flowing to Leatherwood Creek beyond the fence.											

Photograph	er:	Tony N	<b>M</b> orris		Witness:	None	None				
Photo #	4	Of	8		Date:	12/31/09	Time:	11:33			
T			C 1	 1111		1 0	•				

**Description:** A pile of dewatered sludge which has been stored long enough for seeds to sprout.



	Water Division NPDES Photographic Evidence Sheet											
Location: Eureka Springs POTW, Carroll County												
Photographer	r: [	Tony N	<i>M</i> orris		Witness:	None						
Photo #	5	Of	8		Date:	12/31/09	Time:	11:46				

**Description:** Dewatered sludge spilling out of the door in the filter press building.



 Photographer:
 Tony Morris
 Witness:
 None

 Photo #
 6
 Of
 8
 Date:
 12/31/09
 Time:
 11:34

**Description:** Sludge recently spilled in the plant area.



